


Niagara Air Parts, Inc.

2221 Niagara Falls Blvd., Niagara Falls, New York, 14304

Ph: 800-565-4268 Fax 705-326-8105 Int: 705-326-1368

E – mail: sales@niagaraairparts.com Website: niagaraairparts.com

1971890 New Pull Start Clutch



Fits all small C-75, 85, 90, 0-200 & 0-300 Continental engines configured for a Pull Starter.

FAA / STC

Solid non-cracking core, built with 5 rollers Unlike the Delco Remy 4 roller. The use of 5 smaller rollers allows for a thicker outer wall on the body, which in turn eliminates the “bulging” effect that commonly cracks the body on the 40 year old, Delco-Remy models.

Warranty

Six (6) months or 100 hours tach time which ever comes first.